

This exploded view diagram illustrates the assembly of a power tool, likely a reciprocating saw. The components are numbered 1 through 42. The diagram shows the main housing (12), the motor assembly (2), the blade (40), and various internal components like the trigger switch (13), the blade guide (14), and the blade clamp (15). The assembly is shown in a disassembled state to identify individual parts and their relative positions.

